
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/23/2009
Test to be performed: Ground Condition: Smoke Dyed Water X Dry ✓ Damp Wet		Supervisor: JAW
Manhole_ID: S03SS_002MH	Test ID: <u>D1032-022047</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo Observation	on Obs_Remarks
0		Manhole	S05SS_016MH
4		Dye Test V	isible @ IR, 0.1gpm
7		Dye Test V	isible @ IR, 0.2gpm
10.10000038		Dye Test V	isible @ IR, <0.1gpm
13		Dye Test V	isible @ IR, 0.1gpm
16.29999924		Dye Test V	isible @ IR, 0.5gpm
19.39999962		Dye Test V	isible @ IR, 0.1gpm
22.39999962		Dye Test V	isible @ IR, 0.1gpm
26.5		Dye Test V	isible @ IR, 0.2gpm
29.39999962		Dye Test V	isible @ IR, 0.1gpm
30.29999924	02	Tap Factor	y Active 0.1gpm

City of Baltimore Wet Smoke and Dyec	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/23/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ☑ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S03SS_002MH	Test ID: <u>D1032-022047</u>	Notification Made: NA (Residents, Fire, 311)
34	Abandoned Survey DYE FLO	OOD COMPLETED